

ADVERSE EVENT INVESTIGATION								
Part 1 - Overview								
Adverse Event Re	ported By:			Date and Time of Adverse Event:				
Michael Lees			10.59am on 5th March 2024					
Incident	III Llagith			ent (Please Tick One)	L 7 Dev	lmium	Fotol / Mois	
X	III Health	IVIIIIOI	r Injury	+ 3 Day Injury	+ 7 Day	irijury	Fatal / Majo	rinjury
Forwarded To:	Date and Time Forwarded:							
Steve Eccleshare				3.30pm on 5th March 2024				
Part 2 – Initi	al Assessm	ent						
Brief Details								
What Happened: Tool fell from high level scaffold access ladder and fell through a skylight window landing 2ft away from a member of the hotel staff								
Where Did Adverse Event Happen: Kimpton Clocktower Hotel Gym Tower area / HR office								
What Emergency Measures Were Taken: All operations were ceased immediately								
Who was Involved								
Michael Lees (Bullen Conservation Ltd) Kelly Andreasson, Georgina Haydon & Caroline Rowe (Kimpton Hotel staff)								
Who Witnessed E	vent:							
Michael Lees (Bullen Conservation Ltd) Kelly Andreasson, Georgina Haydon & Caroline Rowe (Kimpton Hotel staff)								
RIDDOR Reportab	le?	<del>Yes</del>	No	Date Reported:		Time Re	ported:	
Has Event been R	To Hotel H&S eported?	Yes	_No-	5 March 2024		11.00a	am	
Entry in Accident		<del>Yes</del>	No N/A	Date Entered:		Time En	tered:	
Entered By: N/A				N/A		N/A		
Actual or Potential for Harm								
Fatal / Major	X	Serious		Minor 🗌		Dam	nage Only	
		Inve	stigation L	evel Required				
Minimal 🗌		Low 🗌		Medium $\Box$			High 🛚	
Initial Assessment	t Carried out by:			Date:				
Steve Eccleshare				5 March 2024				
Signed:			Further Investigation Required: Yes X No					
				Priority: High				
Further Investigation to be Carried Out by the Following People:  Bullen Conservation Ltd &								
IHG Hotel Health & Safey Management								



Part 3 – Investigation and Information Gathering					
Who suffered Injury:	Who else was involved with incident:				
No-one suffered an injury	N/A				
Exactly How did the Incident Happen:  Michael Lees placed a chisel in his pocket whilst he was carrying out his site visit, he climbed down an access ladder and the chisel fell from his pocket and bounced away from the scaffold and fell below through the skylight window					
What Equipment Was Involved:					
Chisel					
What Activity Was Being Carried Out at the Time:					
Visual Site Inspection					
Any Unusual Working Conditions at the Time:					
None					
Were Adequate Safe Working Procedures in Place and w	ere they being followed:				
Hoist, toolbag and drop zone all in place but tool was carried down a ladder					
What Injuries or III Health Effects occurred and to What Area of the Body:					
No injuries occurred - near miss					
How did the injury Occur – What Caused It:					
N/A					
Was the Risk Already Known and if so why wasn't it controlled: Michael Lees thought it would be better to remove the chisel in his pocket rather than it falling from the scaffold lift					
Did the Organisation and Arrangement of the Work influence the Event:					
No					
Was Maintenance and Cleaning Sufficient, If No, Why Not:					
Yes					
Were the People Involved Competent and Suitable:					
Yes					
Did the Workplace Layout Influence the Event:					
No					



Did the Nature or Shape of the Materia	Did the Nature or Shape of the Materials Influence the Event:						
No							
Did Difficulties using the Equipment influence the Event:							
No							
Was Safety Equipment Sufficient:							
Yes							
Any Other Conditions that Influenced	Any Other Conditions that Influenced Event:						
No							
Analysis and Further Action							
	How and Why						
If tools were not carried down an access ladder the incident would not have occurred							
Immediate Causes	Underlying Causes	Root Causes					
Tool fell from clothing pouch	Tools left on scaffold	Poor housekeeping					
Risk Control Measures Needed or Recommended							
<ol> <li>Skylight roof protection</li> <li>Working at heoght refresher training</li> <li>Toolbox talks - Good Housekeeping &amp; Use of Loading/Unloading</li> <li>Further scaffold protection - netting - bird protection</li> <li>Tool lanyards to be used at all times</li> <li>Loading area - hoist provided to be used at all times</li> <li>Update RAMS to include - access ladders not to be used to carry tools</li> <li>Helmets with chin straps to be used (which are already in place)</li> <li>Exclusion zone already in place with material hoist</li> <li>Regular tool box talks - morning pre-activity meetings</li> <li>Do Similar Risks Exist Elsewhere (What and Where?): Yes - other roof areas Protection in place</li> </ol>							
Have Similar Adverse Events Happened Before (Give Details): No							



Part 4 – Risk Control Action Plan								
Risk Control Measures That Need Implementing in the Long and Short Term								
Control Measure	Complet	ion Date	Person Responsible M Lees					
Board protect skylight	w/e 8.3.2024		M Lees					
2. Debris net scaffold	w/e 8.3.2024		M Lees					
3. Tool lanyards in operation	w/e 11.3.2024							
4. Loading bay - exclusion	In operation		M Lees					
5. Hoist & tool bag	In operation		M Lees					
6. Toolbox talks	5.03.2024		S Eccleshare & M Lees					
7. Further training	5.3.2024		M Lees & M Eggleton					
8. Netting to handrails	w/e 8.3.2024		M Lees					
9. Update RAMS & Task Briefing	5.3.2024		M Eggleton					
10. Meeting with hotel	7.3.2024		S Eccleshare					
Risk Assessments and	d Safe Working Proc	edures (SWP) Need	ing Review or Updating					
Risk Assessment / SWP	Complet	ion Date	Person Responsible					
1. Method Statements	Updated Jar	n 2024	Bryan Cooper					
2. Task Briefings	05.03.2024		Max Eggleton					
3. Protection - Task Briefing	05.03.2024		Max Eggleton					
4. Debris netting task briefing	05.03.2024		Max Eggleton					
5.			Wax Eggiotori					
Have the Details of the Adverse Even	it and the Investigation	on Findings been R	ecorded:					
Yes								
1 - 2								
Are there any Trends or Common Ca	uses which suggest	the need for furthe	r investigation:					
No								
Estimated Cost of Adverse Event:								
£500.00								
£300.00								
Members of Investigation Team								
Name		Position						
Steve Eccleshare	Director							
Signed on Behalf of the Investigation	Team							
Name:		Signature:						
Steven Eccleshare								
333.50. 23333.								
Communicate the Findings to the Fol	lowing							
Person Signature			Date					
Ryan Bonser - IHG								
	-							

## The Kimpton Clocktower Hotel, Manchester Investigation Report Photos











